




Worldwide repairs carried out with PolymerMetal®

REP-# 009



Repair of a worn bearing seat on the drive of a bulldozer with MM-metal SS-steelceramic and Hardener yellow.

MultiMetall
the MetalExistenceCompany®