



Worldwide repairs carried out with PolymerMetal[®]

REP-# 019



A worn out bearing bush of a floating dredger was rebuilt using MM-metal SS-steelceramic and Hardener yellow. Besides MM-metal SS-steel liquid type with Hardener yellow liquid was injected into a gap of 4 mm between bearing bush and boom.

MultiMetall
the MetalExistenceCompany[®]