




Worldwide repairs carried out with PolymerMetal®

REP-# 001



Repair of 14 bearing bushes of the gear box, which is destined to the bucket wheel drive of an excavator for the field of open-cast mining. The worn bearing bushes with a diameter of 280 to 580 mm and a width of 130 to 150 mm were reconstructed with MM-metal SS-steelceramic and Hardener yellow. The standstill time of the excavator was considerable reduced to 72 hours.

**MultiMetal**  
the MetalExistenceCompany®