





Worldwide repairs carried out with PolymerMetal®

REP-# 037



A cracked gearbox casing was repaired using MM-metal SS-steelceramic, Hardener yellow and MM-Fabric tape (metal).

MultiMetal
the MetalExistenceCompany®