



Worldwide repairs carried out with PolymerMetal®

REP-# 094



Blocking valves have been reconstructed by using Ceramium. Responsible was serious wear and tear on the steel alloy caused by the clay loam.

MultiMetall
the MetalExistenceCompany®